

# Temperature Ranges

## Ranges, °F

Models	K	A	B ADJ	E J ADJ	G GJ ADJ
Dial Size	1"	1½"	2¼"	3"	5"
-150 - 1000°F			X	X	X
-150 - 700°F			X	X	X
-150 - 500°F			X	X	X
-120 - 100°F				X	
-100 - 400°F				X	
-100 - 200°F				X	
-100 - 100°F			X	X	X
-70 - 230°F		X	X	X	X
-65 - 50°F		X	X		
-50 - 300°F			X	X	X
-50 - 250°F			X	X	X
-50 - 125°F			X	X	
-40 - 120°F			X	X	X
-40 - 160°F	X	X	X	X	X
-20 - 180°F		X	X	X	X
0 - 800°F			X	X	X
0 - 700°F			X	X	
0 - 400°F		X	X	X	
0 - 300°F			X	X	X
0 - 250°F		X	X	X	X
0 - 220°F	X	X	X	X	X
0 - 200°F		X	X	X	X
0 - 150°F		X	X	X	X
0 - 100°F			X	X	X
20 - 240°F		X	X	X	X
25 - 125°F		X	X	X	X
50 - 650°F	X		X	X	X
50 - 550°F				X	
50 - 500°F	X	X	X	X	X
50 - 400°F			X	X	X
50 - 300°F	X	X	X	X	X
50 - 250°F		X	X	X	X
50 - 160°F		X	X		X
100 - 200°F				X	
150 - 750°F		X	X	X	X
200 - 1000°F			X	X	X

## Ranges, °C

Models	K	A	B ADJ	E J ADJ	G GJ ADJ
Dial Size	1"	1½"	2¼"	3"	5"
-100 - 50°C			X	X	X
-75 - 325°C				X	
-70 - 160°C			X	X	X
-70 - 25°C			X	X	X
-50 - 100°C		X	X	X	X
-40 - 40°C				X	
-30 - 30°C	X			X	
-10 - 200°C			X		X
-10 - 110°C	X	X	X	X	X
0 - 400°C			X	X	X
0 - 300°C		X	X	X	X
0 - 250°C		X	X	X	X
0 - 200°C		X	X	X	X
0 - 150°C	X	X	X	X	X
0 - 100°C			X	X	X
0 - 60°C			X	X	
0 - 50°C		X	X	X	
100 - 400°C				X	
100 - 500°C			X		X

## Dual Ranges, °F / °C

Models	A ADJ	B ADJ	E J ADJ	G GJ ADJ
Dial Size	1½"	2¼"	3"	5"
-150 - 700°F -100 - 370°C			X	
-100 - 400°F -70 - 200°C		X	X	
-90 - 130°F -68 - 55°C			X	
0 - 130°F -15 - 50°C		X	X	X
0 - 200°F -10 - 100°C	X			
14 - 230°F -10 - 110°C		X	X	X
50 - 160°F 10 - 70°C			X	
50 - 300°F 10 - 150°C		X	X	X
50 - 550°F 0 - 300°C	X			
50 - 500°F 10 - 260°C		X	X	X
150 - 750°F 65 - 400°C		X	X	X
200 - 1000°F 100 - 530°C			X	

*Marshall*

I N S T R U M E N T S  
www.marshallinstruments.com